

Townships Requiring Hydrogen Sulfide Permit Conditions

COUNTY	TOWNSHIPS
Coshocton	Crawford
Erie	Florence
Guernsey	Center, Londonderry, Madison, Oxford, Spencer, Washington
Harrison	Archer, Athens, Cadiz, Franklin, Freeport, Monroe, Moorefield, North, Nottingham, Stock, Washington
Henry	Richfield
Huron	Fitchville, Townsend, Wakeman, Norwich
Morgan	Bristol, Meigsville
Morrow	All
Noble	Jackson
Richland	Blooming Grove
Summit	Northfield, Stow
Tuscarawas	Clay, Goshen, Mill, Perry, Rush, Salem, Union
Washington	Adams, Aurelius, Palmer, Watertown
Wood	Henry, Portage
Williams	Pulaski