


WELL SYMBOLS

- Permitted location
- ⊘ Expired permit location
- ☀ Gas show
- ☀ Gas well
- ☀/⊘ Plugged gas well
- ☀/● Gas and oil show
- Oil show
- Oil well
- /⊘ Plugged oil well
- ☀/● Gas well with oil show
- /☀ Oil well with gas show
- /☀/⊘ Plugged oil well with gas show
- ☀/● Oil and gas well
- ☀/●/⊘ Plugged oil and gas well
- ☀/●/⊘ Plugged gas well with oil show
- Dry hole
- ☀ Dry hole with gas show
- Dry hole with oil show
- ☀/● Dry hole with oil and gas show
- Injection well
- ⊘ Plugged injection well
- ^{PBWW} ○ Well originally drilled for oil and gas, but converted to a water well
- Brine well
- ⊘ Plugged brine well
- Water supply well
- ⊘ Plugged water supply well
- ⊘ Lost hole
- ^{RAD} ⊘ Radioactive geophysical tools lost in hole
- Observation/monitor well
- ★ Unknown status



PERMIT NUMBERS

- 21234 Standard API permit number for wells permitted between 1936 and present.
- 60118 Standard API permit number for Division of Mines and Division of Oil and Gas "A" number wells, USGS Pepper numbers, Ohio Geological Survey "D" and "L" numbers, and wells with no well identifiers.